



Trimble GNSS OEM Receivers

This document contains late-breaking product information, updates, and troubleshooting tips not covered in the Trimble® GNSS OEM receivers' documentation.

- ▶ Introduction
- ▶ Upgrade Procedure
- ▶ New Features and Changes
- ▶ Documentation Updates
- ▶ Legal Notices

Introduction

This release note describes the improvements made since version 3.42 to the following Trimble GNSS OEM receiver:

- MB-Two
- ABX-Two

With this release, these receivers can use version 3.43 of the firmware.

Upgrade Procedure

Version 3.43 of the firmware (Trimble MB-Two Upgrade V3.43 and Trimble ABX-Two Upgrade V3.43) can be downloaded from the Trimble Support web page. Go to www.intech.trimble.com/support/oem_gnss/receivers-trimble or ftp://ftp.ashtech.com/OEM_Sensor_ADU/MB-Two/Firmware/ and select the applicable product.

There are three ways to load the new firmware:

- Use the Ashcom application
- Use the web interface of the receiver
- Use the MB-Two loader (PC only)

For more information, please refer to the Firmware Upgrade section in the *MB-Two User Manual* or *ABX-Two User Manual*.

Version 3.43
Revision A
January 2018



New Features and Changes

The incorrect date and time in the ZDA message is resolved.

Document Updates

The latest documentation can be found online at www.intech.trimble.com/support/oem_gnss/receivers-trimble.





Legal Notices

Trimble Inc.

Civil Construction & Engineering

10368 Westmoor Drive

Westminster, Colorado 80021

USA

800-361-1249 (toll free in USA)

+1-937-245-5154 Phone

+1-937-233-9441 Fax

www.trimble.com

Copyright and Trademarks

© 2018, Trimble Inc. All rights reserved.

Trimble and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries. All other trademarks are the property of their respective owners.

Release Notice

This is the January 2018 release (Revision A) of the GNSS OEM Receivers' Release Notes. It applies to version 3.43 of the Trimble GNSS OEM Series receivers.

