



# TRIMBLE BD930-UHF UPDATE

## PRODUCT END OF LIFE / END OF MANUFACTURING ANNOUNCEMENT

**Date: March 15, 2018**

Trimble® Integrated Technologies announces this product bulletin to inform our customers of planned product migration activities surrounding our BD930-UHF product as follows:

- The BD930-UHF is now officially in its end of life / end of manufacturing phase.
- Trimble® does not encourage development of any new projects using the BD930-UHF.
- Trimble® cannot guarantee product supply after Q1 2018.
- Trimble® suggests BD930-UHF customers looking for a replacement product should connect with their sales contact to determine the best fit for a replacement product.

### The following part numbers will be affected:

Product	Part Number(s)	Description
Trimble BD930-UHF	91142-01	Trimble BD930-UHF , All options disabled, requires upgrade to output positions
	91142-03	Trimble BD930-UHF, GPS, L1 Autonomous/SBAS, 20Hz
	91142-05	Trimble BD930-UHF, GPS, L1 DGPS Base/Rover, 20Hz
	91142-09	Trimble BD930-UHF, GPS, L1 RTK Base/Rover, 20Hz
	91142-13	Trimble BD930-UHF, GPS, L1/L2/L5 RTK Base/Rover, 20Hz
	91142-14	Trimble BD930-UHF, GPS, L1/L2/L5 RTK Rover, 5Hz
	91142-23	Trimble BD930-UHF, GPS, GLN, L1 Autonomous/SBAS, 20Hz
	91142-25	Trimble BD930-UHF, GPS, GLN, L1 DGPS Base/Rover, 20Hz
	91142-27	Trimble BD930-UHF, GPS, GLN, L1 DGPS Rover, 20Hz
	91142-28	Trimble BD930-UHF, GPS, GLN, L1RTK Base/Rover, 5Hz
	91142-29	Trimble BD930-UHF, GPS, GLN, L1RTK Base/Rover, 20Hz
	91142-32	Trimble BD930-UHF, GPS, GLN, L1/L2/L5 RTK Base/Rover, 5Hz
	91142-33	Trimble BD930-UHF, GPS, GLN, L1/L2/L5 RTK Base/Rover, 20Hz
	91142-34	Trimble BD930-UHF, GPS, GLN, L1/L2/L5 RTK Rover, 5Hz
	91142-35	Trimble BD930-UHF, GPS, GLN, L1/L2/L5 RTK Rover, 20Hz
	91142-56	Trimble BD930-UHF, GPS, GLN, BDS L1 Autonomous/SBAS, 20Hz
	91142-57	Trimble BD930-UHF, GPS, GLN, BDS L1, DGPS Base/Rover, 20Hz
	91142-58	Trimble BD930-UHF, GPS, GLN, BDS, L1/L2/L5 RTK Base/Rover, 5Hz
	91142-59	Trimble BD930-UHF, GPS, GLN, BDS L1/L2/L5 RTK Base/Rover, 20Hz
	91142-63	Trimble BD930-UHF, GPS, GLN, GAL, BDS L1 Autonomous/SBAS, 20Hz
91142-64	Trimble BD930-UHF, GPS, GLN, GAL, BDS L1, DGPS Base/Rover, 5Hz	
91142-65	Trimble BD930-UHF, GPS, GLN, GAL, BDS L1, DGPS Base/Rover, 20Hz	
91142-68	Trimble BD930-UHF, GPS, GLN, GAL, BDS L1, RTK Base/Rover, 5Hz	



Product	Part Number(s)	Description
Trimble BD930-UHF (Cont.)	91142-69	Trimble BD930-UHF, GPS, GLN, GAL, BDS L1, RTK Base/Rover, 20Hz
	91142-77	Trimble BD930-UHF, GPS, GLN, GAL, BDS L1/L2/L5 RTK Base/Rover, 20Hz
	91142-83	Trimble BD930-UHF, GPS, BDS, L1 Autonomous/SBAS, 20Hz
	91142-85	Trimble BD930-UHF, GPS, BDS, L1 DGPS Base/Rover, 20Hz
	91142-88	Trimble BD930-UHF, GPS, BDS, L1/L2/L5 RTK Base/Rover, 5Hz
	91142-89	Trimble BD930-UHF, GPS, BDS, L1/L2/L5 RTK Base/Rover, 20Hz
	91142-90	Trimble BD930-UHF, GPS, GLN, GAL, BDS L1/L2/L5, Heading Only Rover3

**Parts, Servicing and Warranty Information**

The standard Trimble policy for parts, servicing and warranty applies.

**Availability**

The above mentioned products will be available while supplies last.

